

DEPT. OF NATURAL RESOURCES

Nebraska Public Power District - Spencer 89566 492 Ave Spencer, NE 68777



Pete Ricketts, Governor

REF: NE00628

Dear Dam Owner,

As required by State Law, an inspection of your dam has been completed by the Nebraska Department of Natural Resources (NeDNR). NeDNR conducts periodic inspections of more than 2,800 dams statewide as required by *Neb. Rev. Stat.* § 46-1664 to protect downstream life and property from dam failures.

Enclosed is a copy of the *Dam Inspection Checklist* and *Photo Log* completed after the inspection along with a booklet, *Inspection and Maintenance of Your Earthen Dam*. As explained below, you can use the completed *Dam Inspection Checklist* and booklet to better understand and improve the condition of your dam:

- 1. If problems were found during the inspection, a blue check mark, ✓, will appear on the left hand side of the *Dam Inspection Checklist* under *Deficiency Requiring Attention*.
- 2. If you have a blue check mark, ✓, you can find information on how to address the problem in the provided booklet, *Inspection and Maintenance of Your Earthen Dam.* On the *Dam Inspection Checklist*, the number on the line next to the blue check mark, ✓, corresponds to the section on pages 6 through 16 of the booklet.
- After completing the inspection and reviewing available records for your dam, an overall condition
 assessment was made. The condition assessment for your dam can be found near the bottom of the
 Dam Inspection Checklist. The four possible condition assessments are satisfactory, fair, poor, and
 unsatisfactory.

If you have any questions about the inspection, the inspection checklist, or how to improve the condition of your dam, please contact the NeDNR's Dam Safety Section at 402-471-2363.

Sincerely,

Mark Noble

Dam Safety Engineer

Gordon W. "Jeff" Fassett, P.E., Director

Department of Natural Resources

301 Centennial Mall South P.O. Box 94676 Lincoln, Nebraska 68509 **OFFICE** 402-471-2363 **FAX** 402-471-2900

dnr.nebraska.gov




NEBRASKA DEPARTMENT OF NATURAL RESOUCES DAM INSPECTION CHECKLIST

DAM NAME: SPENCER DAM	NID #: NE00628 PLAN #: P-3650G APP #: A-1725 DAM APPROVAL STATUS: Approved		
PRIMARY OWNER: Nebraska Public Power District - Spencer	LOCATION: QRT: NW SEC: 30 TWP: 33 RGE: 11 W COUNTY: Holt STREAM: NIOBRARA RIVER		
89566 492 Ave Spencer, NE 68777	HAZARD CLASS: Significant YEAR COMPLETED: 1927 HYDRAULIC CAPACITY: Adequate		
ADDITIONAL OWNERS: Nebraska Public Power District	DAM HEIGHT: 29 feet DRAINAGE AREA: 7084800 acres MAX.STORAGE: 16487 acre-ft DAM TYPE: RE - Earthfill NORMAL STORAGE: 5306 acre-ft DAM LENGTH: 3700 ft		
	INSPECTED BY: Stacey Kolar & Jeramy Sedlacek INSPECTED: 4/24/2018 REVIEWED BY: Mark Noble		


Deficiency	General Conditions	Remarks (References to 'left' or 'right' are made as i	if facing downstream)	
Requiring	Recent High Water Marks	<u> </u>	,	
Attention	2. Downstream Development	The dam is about 1600 feet upstream (west) of U.S. Highway 281		
	3. Inadequate Vegetative Cover			
	4. Alterations to Dam	A toe drain was constructed along the downstream toe in 2015		
	Crest			
	5. Settlements or Cracks			
	6. Erosion			
	7. Trees			
	8. Rodent Holes			
	Upstream Slope			
	9. Settlements, Slides, or Cracks			
	10. Erosion			
	11. Trees			
	12. Rodent Holes			
	Principal Spillway Inlet	Water Surface EL: 3 feet below top of tainter gates and stop logs Size and Type: Concrete spwy with 4 tainter gate bays & 5 bays of stop	Est Flow Rate: 2000 cfs logs Drawdown: no drawdow	
<u> </u>	13. Spalling, Cracking, or Scaling	Floor of concrete spwy is worn with exposed rebar. Dissipators worn dov		
	14. Leakage			
	15. Inadequate Trash Rack			
	16. Obstructions			
	Auxiliary Spillway	Type and Location: there is no auxiliary spillway		
	17. Obstructions			
	18. Erosion			
	19. Rodent Holes			
	20. Vegetation Condition Inadequate			
	Downstream Slope			
	21. Settlements, Slides, or Cracks			
	22. Erosion			
	23. Trees			
\checkmark	24. Rodent Holes	one found		
	25. Problems at Drain or Well Outlet	Toe drains running water, but appear to need routine cleaning.	Est.Flow Rate:	
\checkmark	26. Seepage or Boils	Wet area just d/s of dam, just N of north service road at toe of slope	Est.Flow Rate:	
	Principal Spillway Outlet	Size and Type: See comments for Principal Spillway Inlet	Est.Flow Rate: 2000 cfs	
$\sqrt{}$	27. Spalling, Cracking, or Scaling	See comments for Principal Spillway Inlet		
	28. Leakage			
	29. Obstruction			
	30. Erosion			
	Plunge Pool/Stilling Basin			
	31. Concrete or Riprap Deterioration			
	32. Outlet Channel Obstruction			
	33. Erosion			

Condition Assessment:	Fair - Deficiencies exist which could lead to dam failure during rare, extreme storm events.
Additional Comments:	The angle iron frame on the 3rd gate in from the northernmost gate appears to be bent.

Typical Dam Configuration in Nebraska



Common Problems at Dams in Nebraska



The findings contained in this report were based on a visual inspection of the dam and a review of available records. A more in-depth evaluation or investigation may reveal additional deficiencies that were not discovered during this inspection. The Department of Natural Resources inspects dams in accordance with the Safety of Dams and Reservoirs Act in order to protect downstream life and property from dam failures (Neb. Rev. Stat. §\$46-1635 and 46-1664). Before constructing, reconstructing, enlarging, altering, breaching, removing, or abandoning a dam in Nebraska, the dam owner is required to obtain the approval of the Department (Neb. Rev. Stat. §46-1646). Every owner of a dam subject to the Safety of Dams and Reservoirs Act and not previously approved by the Department is required to file plans for the dam with an application (Neb. Rev. Stat. §46-1670). A storage permit is required if the dam has a normal storage capacity of 15 acre-feet or more below the lowest open overflow, or if the water in the reservoir will be pumped or released for a beneficial purpose (Neb. Rev. Stat. §46-241). Inspection of the dam and the issuance of this inspection report in accordance with Neb. Rev. Stat. §46-1664, in no way changes the approval status of a dam. If you have questions regarding the approval status of your dam, the approval process, or the need for a storage permit, please contact the Department of Natural Resources at 402-471-2363.



Top of Dam



Downstream Slope



Upstream Slope



Principal Spillway Inlet





Principal Spillway Outlet



Example of deteriorating concrete.



Example of toe drain flow.



Bent framework on gate.

